


## Replacement Parts Diagrams

### HBF600S-CCC

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.




|  |                       |         |                         |         |              |           |      |   |
|--|-----------------------|---------|-------------------------|---------|--------------|-----------|------|---|
| <b>Hamilton Beach</b><br>4421 Waterfront Drive<br>Glen Allen, VA 23060 | Revision Description: |         | Correct Cutter Assembly |         |              |           |      |   |
|  | Request Number:       | DOC9221 | Revision Date:          | 8/22/18 | Approved by: | DOC9221   |      |   |
|  | Issue Code(s):        | CS, SP  | Page:                   | 1 of 4  | Document #:  | 540004400 | Rev: | D |

## Replacement Parts Diagrams


### HBF600S-CCC

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.



#### Not Shown:


Power Cord – 990054201  
Cord Socket – 990064800  
Motor Brush Kits – 990075300  
Jar Sensor – 990084400


|  |                       |         |                         |         |              |           |      |   |
|--|-----------------------|---------|-------------------------|---------|--------------|-----------|------|---|
| <br>Hamilton Beach<br>4421 Waterfront Drive<br>Glen Allen, VA 23060 | Revision Description: |         | Correct Cutter Assembly |         |              |           |      |   |
|  | Request Number:       | DOC9221 | Revision Date:          | 8/22/18 | Approved by: | DOC9221   |      |   |
|  | Issue Code(s):        | CS, SP  | Page:                   | 2 of 4  | Document #:  | 540004400 | Rev: | D |
|  |                       |         |                         |         |              |           |      |   |

Replacement Parts Diagrams

HBF600S-CCC

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.




|  |                       |         |                         |         |              |           |      |   |
|--|-----------------------|---------|-------------------------|---------|--------------|-----------|------|---|
|  <b>Hamilton Beach</b><br>4421 Waterfront Drive<br>Glen Allen, VA 23060 | Revision Description: |         | Correct Cutter Assembly |         |              |           |      |   |
|  | Request Number:       | DOC9221 | Revision Date:          | 8/22/18 | Approved by: | DOC9221   |      |   |
|  | Issue Code(s):        | CS, SP  | Page:                   | 3 of 4  | Document #:  | 540004400 | Rev: | D |

**Replacement Parts Diagrams**


**HBF600S-CCC**


**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.

**Accessories**



**Container Washer**  
BCR100



|  |                       |         |                         |         |              |           |      |   |
|--|-----------------------|---------|-------------------------|---------|--------------|-----------|------|---|
| <br>Hamilton Beach<br>4421 Waterfront Drive<br>Glen Allen, VA 23060 | Revision Description: |         | Correct Cutter Assembly |         |              |           |      |   |
|  | Request Number:       | DOC9221 | Revision Date:          | 8/22/18 | Approved by: | DOC9221   |      |   |
|  | Issue Code(s):        | CS, SP  | Page:                   | 4 of 4  | Document #:  | 540004400 | Rev: | D |